ADDENDUM

Addendum # 2:	
Date:	11/18/20
Client/Project Name:	AISD Pickle ES Renovation
Project Number:	21-0017 PICKL
Owner:	Austin ISD
	4000 S. IH 35 Frontage Road
	Austin, TX 78704
Architect:	Jackson Galloway FGM Architects Inc.
	3520 Bee Caves Rd. Suite 150
	Austin, TX 78746
Completed by:	Brian Cotsworth

This addendum forms a part of the Bidding and Contract Documents and modifies the original
bidding documents: the Drawings dated   10-23-20, the Project Manual dated 23-20. g 0 G 0.006 Tc [(edC /P <<
Acknowledge receipt of this addendum in space provided on Bid Form. FAILURE TO
ACKNOWLEDGE RECEIPT OF ADDENDA ON THE BID FORM MAY DISQUALIFY BID.

CLARIFICATIONS:

C1. There are no Alternates listed for this project.

QUESTIONS & ANSWERS

Q1. Can the Structural Deficiency documents DI   -39056 be provided to help understand the

A1. Yes. Please see attach ed

Bid Documents (061250).

<p style="text-align:center">END OF ADDENDUM NO. 2</p>

PROPOSAL FORM

To: The Board of Trustees
        Austin Independent School District
        4000 S IH 35 Frontage Road
        Austin, Texas 78704

Re: AISD CSP No.: 21CSP051

From: _____
        (Full legal name of firm, including DBA, if applicable)

Project Number: 210017-PICKL / 21CSP051

Project Title: 210017-PICKLE ES REN INo4 29 dR6747b.6 (t)sE-INo4 9a3 Tc 0 TC4sb8op (N)4.osd (1 un1 (b.6 (t

1.	Spall Repairs	12 locations (0.5 SF each

East Exterior Wall Repairs	Qty	Lump Sum	Unit Price
1. Spall Repairs	8 locations (0.5 SF each)	$_____	$_____ SF

General		

Campus: **Pickle ES**

Deficiency ID: **DI-39057**

Location: Main Building   Project #: 210017-PICKL

Bond & Phase: 2017-P4

System: D3030 Cooling Generating Systems

Group: Mechanical

Initial Construction Total: $1,018,31

Name: Heating and Air Conditioning Improvements

Description: Assume replace 50% HVAC Equipment

Comments: Reported that HVAC equipment is close to end of service life, severe corrosion on water heater WH5-1A, exhaust fan EF 2-3 missing cover

Project Manager Notes