ADDENDUM NO. 1

DATE: November 27, 2018

PROJECT: BARBARA JORDAN ELEMENTARY SCHOOL

ADDITIONS & RENOVATIONS

LOCATION: 6711 JOHNNY MORRIS RD, AUSTIN, TX 78724

PROJECT NO: S&C #R092017 / AISD #180011

DISTRIBUTION: 11/27/18

DELIVERED VIA: Email

DELIVERED VIA. EIIIaii

NO. PAGES: 07

PREPARED BY: Smith & Company Architects

This addendum forms a part of the Specifications for the Barbara Jordan Elementary School Additions & Renovations Project S&C #R092017 / AISD #180011 for Austin Independent School District documents posted on October 22, 2018, for the subject project and modifies/add to them as noted below.

CHANGES TO PROJECT MANUAL

GENERAL INFORMATION

1. A

T0 11.04 71.\(\bar{B} \) Tr (d)-1 (u)-1 (m)-1 (s)\(\bar{J} \) J

			
			
			
- —		-	
			
			
			
= ===			
= ===			
			
	_		
	_		
- —			
- —			
= ===			
			
			

2	each	Cisco	SFP-H10GB-CU3M	10GBASE-CU SFP+ Cable 3 Meter, passive	
				SFP-1-4B-CU3M	
_					
_					
-					
					
_					
-					
_					
_					
-					
				-	

AISD STANDARD SPECIFICATIONS REVISION 15 – JUNE 8, 2012

1	each	Cisco	NEW-UWL-11X-S-SLE-	New CUWL Std Edition 11.x Usr, SLED/Govt/Edu Only, 1 Usr	
4	each	Cisco	CON-ECMU-CUW1LXK-SWSS	UPGRADES Unified Workspace Licensing v. 11.	
				Office Phones	
1	each	Cisco	CP-7841 K9=	Cisco UC Phone 7841	
1	each	Cisco	NEW-UWL-11X-S-SLE-	New CUWL Std Edition 11.x Usr, SLED/Govt/Edu Only, 1 Usr	
1	each	Cisco	CON-ECMU-CUW1LXK-SWSS	UPGRADES Unified Workspace Licensing v. 11.	1
				Classroom Phones	
4	each	Cisco	CP-7841 K9=	Cisco UC Phone 7841	
4	each	Cisco	NEW-UWL-11X-S-SLE-	New CUWL Std Edition 11.x Usr, SLED/Govt/Edu Only, 1 Usr	
4	each	Cisco	CON-ECMU-CUW1LXK-SWSS	UPGRADES Unified Workspace Licensing v. 11.	
				Conference Phones	
4	each	Cisco	CP-8831-K9=	Cisco 8831 Base/Control Panel for North America	
4	each	Cisco	NEW-UWL-11X-S-SLE-	New CUWL Std Edition 11.x Usr, SLED/Govt/Edu Only, 1 Usr	
4	each	Cisco	CON-ECMU-CUW1LXK-SWSS	UPGRADES Unified Workspace Licensing v. 11.	
				VOIP Router required for MDF	
1	each	Cisco	ISR-4331-V/K9-	Cisco ISR 4331 UC Bundle, PVDM4-32, UC License, CUBEE10	
4	each	Cisco	CON-SNT-ISR4331V- SNCT	SNCT-8X5XNBD-Cisco-ISR-4331-UC-Bundle, PVDM4-32-UC-L	
1	each	Cisco	SL-4330-IPB-K9-	-Base License for Cisco-ISR 4330 Series	
1	each	Cisco	SL-4330-UC-K9	-Unified Communications License for Cisco ISR 4330 Series	
1	each	Cisco	PWR-4330-AC	AC Power Supply for Ciasco ISR 4330	
4	each	Cisco	CAB-AC- AC	-AC-Power Cord (North America), C13, NEMA 5-15P, 2.1m	
2	each	Cisco	NIM-BLANK	Blank faceplate for NIM slot on Cisco ISR 4400	
1	each	Cisco	M-S-BLANK	Removable faceplate for SM-slot on Cisco 2900,3900,4400 ISR	
1	each	Cisco	MEM-4300-4G-	4G DRAM (2G+2G) for Cisco ISR 4330, 4350	
1	each	Cisco	MEM-FLSH-4G-	Flash Memory for Cisco ISR 4300 (Soldered on motherboard)	
1	each	Cisco	PVDM4-32-	-32-channel DSP module	
1	each	Cisco	SISR4300UK9-316-	Cisco ISR 4300 Series IOS XE Universal	
4	each	Cisco	NIM-4FXO=	4-port-Network Interface Module ~ FXO (Universal)	
4	each	Cisco	NIM-4FXS≡	4-Port Network Interface Module - FXS, FXS-E and DID	

- 1. Include installation costs in purchase amount only where indicated as part of the allowance.
- 2. If requested, prepare explanation and documentation to substantiate distribution of overhead costs and other margins claimed.
- 3. Submit substantiation of a change in scope of work, if any, claimed in Change Orders related to unit-cost allowances.
- 4. Owner reserves the right to establish the quantity of work-in-place by independent quantity survey, measure, or count.
- B. Submit claims for increased costs because of a change in scope or nature of the allowance described in the Contract Documents, whether for the purchase order amount or Contractor's handling, labor, installation, overhead, and profit.
 - 1. Do not include Contractor's or subcontractor's indirect expense in the Change Order cost amount unless it is clearly shown that the nature or extent of work has changed from what could have been foreseen from information in the Contract Documents.

2.